Qty:

1 Um:

Each

: BASKET BASE ASSEMBLY (350)

: D2221

: N/A

: F/B1 AIU:

: 4/5/2006

: D2221/D2235

Wednesday, 3/29/2006 1:07:16 PM

Linda Lacelle

## **Process Sheet**

**Drawing Name** 

**Part Number** 

Material

**Due Date** 

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

mer Number دُ : CU-DAR001 Dart Helicopters Services

: 26391A

stimate Number

: 10189

P.O. Number

:NIA

This Issue Prsht Rev

First Issue

**Previous Run** 

: 3/29/2006

: NC

: NIA : 26390A

S.O. No. : NIA

Type

: LARGE FAB ASSY

COMMENT Pelou

Checked & Approved By

Comment

Written By

: Est Rev:J 05.09.02

Added D3442-1KJ/JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

D31661 1.0

Basket Hoop

4.0000 Each(s)/Unit Total:

Comment: Qty.: Pick:

**Qty Part Number** 

4 D3166-1

Description Batch

Basket Hinge

4.0000 Each(s)

CPL

06.04.09

2.0

D22323

2.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Pick:

Comment: Qty.:

**Qty Part Number** 

Description \_Batch

2 D2232-3 Hinge bracket <u>1525239</u>

CPL 06.04.10

3.0

D2325

Support Gusset (350 Bask



Comment: Qty.: 4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick:

**Qty Part Number** 

Description

4 D2325

Support Gusset

CPL 06.04.10

4.0

D23273

Spacer Bushing



2.0000 Each(s)/Unit

Comment: Qty.:

Total:

2.0000 Each(s)

Pick:

**Qty Part Number** 

Description

2 D2327-3 Bushing

CPC 06.04.10

Dart Ae	rospace l	Ltd							
W/O:			٧	ORK ORDER CHANGES					
DATE	STEP				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		*							
		*							
Part No	•	PAR #:	_ Fault Ca	tegory: NC	R: Yes	No DQ	A:	Date: _	
					QA: N	/C Close	d:	_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMANCI	E (NCR	2)			
		Description of NC	Corrective Action Section			Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect		Chief Eng	QC Inspector
								-	
	9					•			
		:						,	
				**					

NOTE: Date & initial all entries

Date: Wednesday, 3/29/2006 1:07:16 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001. Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 26391A Part Number: D2221 Job Number: Seq. #: **Description: Machine Or Operation:** 5.0 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description CPC 06.04.11 2 D2581 Mounting Bracket 6.0 D34421 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D3442-1 Shim PC 06.04.10 M304EX07516F Expanded Metal Flat Stai 7.0 Comment: Qty.: 39.6900 sf(s)/Unit Total: 39.6900 sf(s) Pick: **Qty Part Number** Description Batch CPC 06.04/1 36 sf M304EX0.75-16F Expanded Metal M304TS0750W065 Comment: Qty.: CPC 06.04.10 29.4000 f(s)/Unit Total: 29.4000 f(s) Pick: M100282-51" 3/4" x 3/4" x 0.063 wall 304/316 SStubing 304/316 Batch: M1000Z3  $\rightarrow$  93,01" 9.0 LARGE FAB **Comment:** LARGE FABRICATION RESOURCE 1 CPC 06.04.24 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding

5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required

Dart Ae	rospace Lto									
W/O:		WORK ORDER CHANGES								
DATE	STEP	PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
;		•4.0								
						·		<del></del>		
				E		· · · · · · · · · · · · · · · · · · ·				
Part No	: PAR #:		Fault Category:	NCR: Yes (No		No DQ	DQA: Dat		ate: <u>06/05/04</u>	
			A)		QA:	N/C Close	d:	_ Date: _		
		· ·	WORK OPDED NO	NI CONFOR	MANCE (NC	D)				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE		P Description of NC Section A		Corrective Action Section	Verification						
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
					÷						

NOTE: Date & initial all entries

Date: Wednesday, 3/29/2006 1:07:16 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 26391A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation: Description:** DDIMENSIONAL & WELDING INSPECTION QC9/6 10.0 Comment: DDIMENSIONAL & WELDING INSPECTION POWDER COATING 11.0 POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSI 12.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 13.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Seal support gusset seam with white sikaflex-291 Batch: 166 470 Expiry date: \_\_ DOCUMENT CONTROL 14.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Dart Ae	rospace l	_td							
W/O:			WO	<b>RK ORDER CHANGES</b>					
DATE	STEP	PR	OCEDURE CHAI	CEDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,		×.			-		
		4							1
				E-					
Part No	•	PAR #:	Fault Categ	ory: N	ICR: Yes	No DQ	<b>A</b> :	Date:	
			•		QA: N	C Close	d:	_ Date: _	
NCR:		,	WORK ORDE	R NON-CONFORMANC			*		
DATE	0750	Description of NC	Corrective Action Section B			Verific	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		Section C	Chief Eng	QC Inspector
•									
	<del> </del>	MIN'T 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				+			<del> </del>

NOTE: Date & initial all entries